



Legal and technical information pertaining to radio emitting devices

COUNTRY: INDONESIA

LABEL NAME: SDPPI SRD



Special Instructions for marking placement:

The Certificate bearer shall make and attach the label on each instrument and set of equipment and on the packaging before it is sold in Indonesia.

Certificate holder must attach warning sign on their Telecommunication tools and/or devices except for short range devices.

The packaging label must contain the QR code that can be found on the bottom right of each certificate.

If the labeling is not possible to be attached to the device then it is possible for the applicant to print the label in the user manual or installation instructions.

It is recommended that this document is kept alongside or inside the owner's manual

This document is available at the following web address:
www.audi.com/generalinfo

Audi hereby informs you of AUDI AG's declaration that the following components conform to the technical requirements as set out by SDPPI SRD.

 - Radio service















































 - Models



























 - Requirements for SRD



- SDPPI Warning Sign

AUDI AG, Auto-Union-Straße 1,
D-85045 Ingolstadt ©
11/2023 AUDI AG

| 📶 | 🔗 | 📄 | | | | | | | | | | | | | | | |
|--|--|--|--|--|--|---|---|--|--|--|--|--|--|--|--|--|--|
| <p>Main Unit MIB</p>  <p>Control Unit ConBox High</p>  | <p>A1,Q2,A3,Q3,A4 A5,Q4e-tron,Q5 A6/e-tron,A7 Q6e-tron,Q7 A8, Q8/e-tron e-tron/GT,TT,R8</p> | <div style="border: 1px dashed black; padding: 5px;">  <p style="font-size: 8px;">Peringatan: Memeriksa pembaruan sertifikat pada sistem kendaraan sebelum prosedur pemrograman dilakukan.</p> <table border="1" style="width: 100%; text-align: center;"> <tr> <td style="width: 33%;"> <p>Nomor Sertifikat 93784/SDPPI/2023 PLG ID 4334 Model: MIB3 TOP2</p>  </td> <td style="width: 33%;"> <p>Nomor Sertifikat 63852/SDPPI/2019 PLG ID 4334 Model: MIB3 TOP</p>  </td> <td style="width: 33%;"> <p>Nomor Sertifikat 39689/SDPPI/2017 PLG ID 4334 Model: MIB2 MU</p>  </td> </tr> <tr> <td colspan="3"> <p>Nomor Sertifikat 93785/SDPPI/2023 PLG ID 4334 Model: MIB3 TOP2</p>  </td> </tr> <tr> <td colspan="3"> <p>Nomor Sertifikat 62957/SDPPI/2019 PLG ID 4334 Model: CONBOX-H</p>  </td> </tr> <tr> <td colspan="3"> <p>Nomor Sertifikat 62958/SDPPI/2019 PLG ID 4334 Model: CONBOX-H</p>  </td> </tr> <tr> <td colspan="3"> <p>Nomor Sertifikat 86816/SDPPI/2022 PLG ID 4334 Model: TKCMOD11000</p>  </td> </tr> </table> </div> | <p>Nomor Sertifikat 93784/SDPPI/2023 PLG ID 4334 Model: MIB3 TOP2</p>  | <p>Nomor Sertifikat 63852/SDPPI/2019 PLG ID 4334 Model: MIB3 TOP</p>  | <p>Nomor Sertifikat 39689/SDPPI/2017 PLG ID 4334 Model: MIB2 MU</p>  | <p>Nomor Sertifikat 93785/SDPPI/2023 PLG ID 4334 Model: MIB3 TOP2</p>  | | | <p>Nomor Sertifikat 62957/SDPPI/2019 PLG ID 4334 Model: CONBOX-H</p>  | | | <p>Nomor Sertifikat 62958/SDPPI/2019 PLG ID 4334 Model: CONBOX-H</p>  | | | <p>Nomor Sertifikat 86816/SDPPI/2022 PLG ID 4334 Model: TKCMOD11000</p>  | | |
| <p>Nomor Sertifikat 93784/SDPPI/2023 PLG ID 4334 Model: MIB3 TOP2</p>  | <p>Nomor Sertifikat 63852/SDPPI/2019 PLG ID 4334 Model: MIB3 TOP</p>  | <p>Nomor Sertifikat 39689/SDPPI/2017 PLG ID 4334 Model: MIB2 MU</p>  | | | | | | | | | | | | | | | |
| <p>Nomor Sertifikat 93785/SDPPI/2023 PLG ID 4334 Model: MIB3 TOP2</p>  | | | | | | | | | | | | | | | | | |
| <p>Nomor Sertifikat 62957/SDPPI/2019 PLG ID 4334 Model: CONBOX-H</p>  | | | | | | | | | | | | | | | | | |
| <p>Nomor Sertifikat 62958/SDPPI/2019 PLG ID 4334 Model: CONBOX-H</p>  | | | | | | | | | | | | | | | | | |
| <p>Nomor Sertifikat 86816/SDPPI/2022 PLG ID 4334 Model: TKCMOD11000</p>  | | | | | | | | | | | | | | | | | |
| <p>Remote Key</p>  <p>Central control unit</p> <p>Emergency starting unit</p> | <p>A1,Q2,A3,Q3,A4 A5,Q4e-tron,Q5 A6/e-tron,A7 Q6e-tron,Q7 A8, Q8/e-tron e-tron/GT,TT,R8</p> | <table border="1" style="width: 100%; text-align: center;"> <tr> <td style="width: 25%;"> <p>Nomor Sertifikat 82927/SDPPI/2022 PLG ID 4334 Model: FS14P70M</p>  </td> <td style="width: 25%;"> <p>Nomor Sertifikat 82122/SDPPI/2022 PLG ID 4334 Model: FS197</p>  </td> <td style="width: 25%;"> <p>Nomor Sertifikat 81814/SDPPI/2022 PLG ID 4334 Model: AK1A</p>  </td> <td style="width: 25%;"> <p>Nomor Sertifikat 93257/SDPPI/2023 PLG ID 4334 Model: AK2</p>  </td> </tr> <tr> <td> <p>Nomor Sertifikat 85385/SDPPI/2022 PLG ID 4334 Model: FS1270M</p>  </td> <td> <p>Nomor Sertifikat 66078/SDPPI/2020 PLG ID 4334 Model: FS1270</p>  </td> <td> <p>Nomor Sertifikat 95169/SDPPI/2023 PLG ID 4334 Model: B8N</p>  </td> </tr> </table> | <p>Nomor Sertifikat 82927/SDPPI/2022 PLG ID 4334 Model: FS14P70M</p>  | <p>Nomor Sertifikat 82122/SDPPI/2022 PLG ID 4334 Model: FS197</p>  | <p>Nomor Sertifikat 81814/SDPPI/2022 PLG ID 4334 Model: AK1A</p>  | <p>Nomor Sertifikat 93257/SDPPI/2023 PLG ID 4334 Model: AK2</p>  | <p>Nomor Sertifikat 85385/SDPPI/2022 PLG ID 4334 Model: FS1270M</p>  | <p>Nomor Sertifikat 66078/SDPPI/2020 PLG ID 4334 Model: FS1270</p>  | <p>Nomor Sertifikat 95169/SDPPI/2023 PLG ID 4334 Model: B8N</p>  | | | | | | | | |
| <p>Nomor Sertifikat 82927/SDPPI/2022 PLG ID 4334 Model: FS14P70M</p>  | <p>Nomor Sertifikat 82122/SDPPI/2022 PLG ID 4334 Model: FS197</p>  | <p>Nomor Sertifikat 81814/SDPPI/2022 PLG ID 4334 Model: AK1A</p>  | <p>Nomor Sertifikat 93257/SDPPI/2023 PLG ID 4334 Model: AK2</p>  | | | | | | | | | | | | | | |
| <p>Nomor Sertifikat 85385/SDPPI/2022 PLG ID 4334 Model: FS1270M</p>  | <p>Nomor Sertifikat 66078/SDPPI/2020 PLG ID 4334 Model: FS1270</p>  | <p>Nomor Sertifikat 95169/SDPPI/2023 PLG ID 4334 Model: B8N</p>  | | | | | | | | | | | | | | | |

| 📶 | 🔗 | 📄 | | | | | | | | |
|---|---|---|--|---|---|--|---|---|---|--|
| <p>Remote Key</p>  <p>Central control unit</p> <p>Emergency starting unit</p> | <p>A1,Q2,A3,Q3,A4 A5,Q4e-tron,Q5 A6/e-tron,A7 Q6e-tron,Q7 A8, Q8/e-tron e-tron/GT,TT,R8</p> | <table border="1" style="width: 100%; text-align: center;"> <tr> <td style="width: 25%;"> <p>Nomor Sertifikat 80846/SDPPI/2022 PLG ID 4334 Model: 013854</p>  </td> <td style="width: 25%;"> <p>Nomor Sertifikat 66732/SDPPI/2020 PLG ID 4334 Model: MQB-B H</p>  </td> <td style="width: 25%;"> <p>Nomor Sertifikat 66602/SDPPI/2020 PLG ID 4334 Model: MQB-B B</p>  </td> <td style="width: 25%;"> <p>Nomor Sertifikat 82107/SDPPI/2022 PLG ID 4334 Model: I22U</p>  </td> </tr> <tr> <td> <p>Nomor Sertifikat 85367/SDPPI/2022 PLG ID 4334 Model: BCMevoC</p>  </td> <td> <p>Nomor Sertifikat 84666/SDPPI/2022 PLG ID 4334 Model: BCMevo5</p>  </td> <td> <p>Nomor Sertifikat 74303/SDPPI/2021 PLG ID 4334 Model: BCM PQ37H</p>  </td> <td> <p>Nomor Sertifikat 82384/SDPPI/2022 PLG ID 4334 Model: E3HCP422</p>  </td> </tr> </table> | <p>Nomor Sertifikat 80846/SDPPI/2022 PLG ID 4334 Model: 013854</p>  | <p>Nomor Sertifikat 66732/SDPPI/2020 PLG ID 4334 Model: MQB-B H</p>  | <p>Nomor Sertifikat 66602/SDPPI/2020 PLG ID 4334 Model: MQB-B B</p>  | <p>Nomor Sertifikat 82107/SDPPI/2022 PLG ID 4334 Model: I22U</p>  | <p>Nomor Sertifikat 85367/SDPPI/2022 PLG ID 4334 Model: BCMevoC</p>  | <p>Nomor Sertifikat 84666/SDPPI/2022 PLG ID 4334 Model: BCMevo5</p>  | <p>Nomor Sertifikat 74303/SDPPI/2021 PLG ID 4334 Model: BCM PQ37H</p>  | <p>Nomor Sertifikat 82384/SDPPI/2022 PLG ID 4334 Model: E3HCP422</p>  |
| <p>Nomor Sertifikat 80846/SDPPI/2022 PLG ID 4334 Model: 013854</p>  | <p>Nomor Sertifikat 66732/SDPPI/2020 PLG ID 4334 Model: MQB-B H</p>  | <p>Nomor Sertifikat 66602/SDPPI/2020 PLG ID 4334 Model: MQB-B B</p>  | <p>Nomor Sertifikat 82107/SDPPI/2022 PLG ID 4334 Model: I22U</p>  | | | | | | | |
| <p>Nomor Sertifikat 85367/SDPPI/2022 PLG ID 4334 Model: BCMevoC</p>  | <p>Nomor Sertifikat 84666/SDPPI/2022 PLG ID 4334 Model: BCMevo5</p>  | <p>Nomor Sertifikat 74303/SDPPI/2021 PLG ID 4334 Model: BCM PQ37H</p>  | <p>Nomor Sertifikat 82384/SDPPI/2022 PLG ID 4334 Model: E3HCP422</p>  | | | | | | | |
| <p>Wireless Charging</p> | <p>A1,Q2,A3,Q3,A4 A5,Q4e-tron,Q5 A6/e-tron,A7 Q6e-tron,Q7 A8, Q8/e-tron e-tron/GT,TT,R8</p> | <p>Nomor Sertifikat 89225/SDPPI/2023 PLG ID 4334 Model: WCH-304</p>  | | | | | | | | |

| SCON | A1,Q2,A3,Q3,A4 A5,Q4e-tron,Q5 A6/e-tron,A7 Q6e-tron,Q7 A8, Q8/e-tron e-tron/GT,TT,R8 | <table border="1"> <tr> <td colspan="4" data-bbox="398 108 1041 183"> Nomor Sertifikat 65220/SDPPI/2019 PLG ID 4334 Model:SCON </td> </tr> <tr> <td colspan="4" data-bbox="398 183 1041 331"> </td> </tr> </table> | | | | Nomor Sertifikat 65220/SDPPI/2019 PLG ID 4334 Model:SCON | | | | | | | |
|--|---|---|--|--|---|--|--|---|--|--|--|--|--|
| Nomor Sertifikat 65220/SDPPI/2019 PLG ID 4334 Model:SCON | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Radar sensors | A1,Q2,A3,Q3,A4 A5,Q4e-tron,Q5 A6/e-tron,A7 Q6e-tron,Q7 A8, Q8/e-tron e-tron/GT,TT,R8 | <table border="1"> <tr> <td data-bbox="398 571 546 646"> Nomor Sertifikat 69460/SDPPI/2020 PLG ID 4334 Model: R3TR </td> </tr> <tr> <td data-bbox="398 646 546 798"> </td> </tr> </table> | Nomor Sertifikat 69460/SDPPI/2020 PLG ID 4334 Model: R3TR | | <table border="1"> <tr> <td data-bbox="577 571 725 646"> Nomor Sertifikat 73816/SDPPI/2021 PLG ID 4334 Model: LRR4R </td> </tr> <tr> <td data-bbox="577 646 725 798"> </td> </tr> </table> | Nomor Sertifikat 73816/SDPPI/2021 PLG ID 4334 Model: LRR4R | | <table border="1"> <tr> <td data-bbox="734 571 882 646"> Nomor Sertifikat 73094/SDPPI/2021 PLG ID 4334 Model: RS4 </td> </tr> <tr> <td data-bbox="734 646 882 798"> </td> </tr> </table> | Nomor Sertifikat 73094/SDPPI/2021 PLG ID 4334 Model: RS4 | | <table border="1"> <tr> <td data-bbox="891 571 1039 646"> Nomor Sertifikat 74525/SDPPI/2021 PLG ID 4334 Model:MRR1R </td> </tr> <tr> <td data-bbox="891 646 1039 798"> </td> </tr> </table> | Nomor Sertifikat 74525/SDPPI/2021 PLG ID 4334 Model:MRR1R | |
| Nomor Sertifikat 69460/SDPPI/2020 PLG ID 4334 Model: R3TR | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Nomor Sertifikat 73816/SDPPI/2021 PLG ID 4334 Model: LRR4R | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Nomor Sertifikat 73094/SDPPI/2021 PLG ID 4334 Model: RS4 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Nomor Sertifikat 74525/SDPPI/2021 PLG ID 4334 Model:MRR1R | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | <table border="1"> <tr> <td data-bbox="398 825 546 900"> Nomor Sertifikat 77225/SDPPI/2021 PLG ID 4334 Model: ARSS10 </td> </tr> <tr> <td data-bbox="398 900 546 1051"> </td> </tr> </table> | Nomor Sertifikat 77225/SDPPI/2021 PLG ID 4334 Model: ARSS10 | | <table border="1"> <tr> <td data-bbox="577 825 725 900"> Nomor Sertifikat 84482/SDPPI/2022 PLG ID 4334 Model: F5CP42 </td> </tr> <tr> <td data-bbox="577 900 725 1051"> </td> </tr> </table> | Nomor Sertifikat 84482/SDPPI/2022 PLG ID 4334 Model: F5CP42 | | <table border="1"> <tr> <td data-bbox="734 825 882 900"> Nomor Sertifikat 85926/SDPPI/2022 PLG ID 4334 Model: F5CP42 </td> </tr> <tr> <td data-bbox="734 900 882 1051"> </td> </tr> </table> | Nomor Sertifikat 85926/SDPPI/2022 PLG ID 4334 Model: F5CP42 | | | | |
| Nomor Sertifikat 77225/SDPPI/2021 PLG ID 4334 Model: ARSS10 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Nomor Sertifikat 84482/SDPPI/2022 PLG ID 4334 Model: F5CP42 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Nomor Sertifikat 85926/SDPPI/2022 PLG ID 4334 Model: F5CP42 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |

| | A1,Q2,A3,Q3,A4 A5,Q4e-tron,Q5 A6/e-tron,A7 Q6e-tron,Q7 A8, Q8/e-tron e-tron/GT,TT,R8 | <table border="1"> <tr> <td data-bbox="1518 108 1666 183"> Nomor Sertifikat 63140/SDPPI/2019 PLG ID 4334 Model: 17101033 </td> </tr> <tr> <td data-bbox="1518 183 1666 335"> </td> </tr> </table> | Nomor Sertifikat 63140/SDPPI/2019 PLG ID 4334 Model: 17101033 | | <table border="1"> <tr> <td data-bbox="1697 108 1845 183"> Nomor Sertifikat 64641/SDPPI/2019 PLG ID 4334 Model: FPK Gen 1 </td> </tr> <tr> <td data-bbox="1697 183 1845 335"> </td> </tr> </table> | Nomor Sertifikat 64641/SDPPI/2019 PLG ID 4334 Model: FPK Gen 1 | | <table border="1"> <tr> <td data-bbox="1854 108 2002 183"> Nomor Sertifikat 62637/SDPPI/2019 PLG ID 4334 Model: 17101002 </td> </tr> <tr> <td data-bbox="1854 183 2002 335"> </td> </tr> </table> | Nomor Sertifikat 62637/SDPPI/2019 PLG ID 4334 Model: 17101002 | | <table border="1"> <tr> <td data-bbox="2011 108 2159 183"> Nomor Sertifikat 62638/SDPPI/2019 PLG ID 4334 Model: 17101001 </td> </tr> <tr> <td data-bbox="2011 183 2159 335"> </td> </tr> </table> | Nomor Sertifikat 62638/SDPPI/2019 PLG ID 4334 Model: 17101001 | |
|---|---|--|--|--|---|---|--|--|--|--|--|--|--|
| Nomor Sertifikat 63140/SDPPI/2019 PLG ID 4334 Model: 17101033 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Nomor Sertifikat 64641/SDPPI/2019 PLG ID 4334 Model: FPK Gen 1 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Nomor Sertifikat 62637/SDPPI/2019 PLG ID 4334 Model: 17101002 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Nomor Sertifikat 62638/SDPPI/2019 PLG ID 4334 Model: 17101001 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | <table border="1"> <tr> <td data-bbox="1518 378 1666 453"> Nomor Sertifikat 63078/SDPPI/2019 PLG ID 4334 Model: 18020533 </td> </tr> <tr> <td data-bbox="1518 453 1666 604"> </td> </tr> </table> | Nomor Sertifikat 63078/SDPPI/2019 PLG ID 4334 Model: 18020533 | | <table border="1"> <tr> <td data-bbox="1697 378 1845 453"> Nomor Sertifikat 63077/SDPPI/2019 PLG ID 4334 Model: 18020533 </td> </tr> <tr> <td data-bbox="1697 453 1845 604"> </td> </tr> </table> | Nomor Sertifikat 63077/SDPPI/2019 PLG ID 4334 Model: 18020533 | | <table border="1"> <tr> <td data-bbox="1854 378 2002 453"> Nomor Sertifikat 63079/SDPPI/2019 PLG ID 4334 Model: 18020533 </td> </tr> <tr> <td data-bbox="1854 453 2002 604"> </td> </tr> </table> | Nomor Sertifikat 63079/SDPPI/2019 PLG ID 4334 Model: 18020533 | | <table border="1"> <tr> <td data-bbox="2011 378 2159 453"> Nomor Sertifikat 63138SDPPI/2019 PLG ID 4334 </td> </tr> <tr> <td data-bbox="2011 453 2159 604"> </td> </tr> </table> | Nomor Sertifikat 63138SDPPI/2019 PLG ID 4334 | |
| Nomor Sertifikat 63078/SDPPI/2019 PLG ID 4334 Model: 18020533 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Nomor Sertifikat 63077/SDPPI/2019 PLG ID 4334 Model: 18020533 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Nomor Sertifikat 63079/SDPPI/2019 PLG ID 4334 Model: 18020533 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Nomor Sertifikat 63138SDPPI/2019 PLG ID 4334 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | <table border="1"> <tr> <td data-bbox="1518 647 1666 722"> Nomor Sertifikat 63139SDPPI/2019 PLG ID 4334 Model: 17101033 </td> </tr> <tr> <td data-bbox="1518 722 1666 871"> </td> </tr> </table> | | | | Nomor Sertifikat 63139SDPPI/2019 PLG ID 4334 Model: 17101033 | | | | | | | |
| Nomor Sertifikat 63139SDPPI/2019 PLG ID 4334 Model: 17101033 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |